



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 18  
2.KERROS

+20.30  
PRSH B


2H+KK/B  
44.5




KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 19  
2.KERROS




KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 20  
2.KERROS



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 21  
3.KERROS





KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 22  
3.KERROS

PRSH B  
+23.10

B15

B15

B15


B15

B22


SK

2H+KK/B  
44.5


KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 23  
3.KERROS




KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 24  
3.KERROS





KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 25  
4.KERROS







KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 26  
4.KERROS




KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 27  
4.KERROS



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 28  
4.KERROS



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 29  
5.KERROS



H4000

PRSH B  
+28.70


KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 30  
5.KERROS

B30


SK +

2H+KK/B1  
44.5

KL



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 31  
5.KERROS



H4000

PRSH B  
+28.70


B31

SK


3H+K/B2  
74.5


KL

KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 32  
5.KERROS




KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 13  
1.KERROS






KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 14  
1.KERROS



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 15  
1.KERROS



+16.75

+16.825

B15

PRSH B  
+17.50

B15

B15

B15


B15

SK

3H+K/B2  
74.5

KL

KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 16  
1.KERROS



KIINT.-OY RASTILANTORI  
MERI-RASTILAN TIE 6 B 17  
2.KERROS

